



OUTLOOK

SHADE FABRIC CARE & WARRANTY

AUGUST 2010

Fabric Care

TO OBTAIN THE MAXIMUM LIFE FROM OUTLOOK MESH PRODUCTS, THE FOLLOWING POINTS SHOULD BE NOTED:

1. Keep the fabric clean by brushing regularly both on the top and underside with a soft bristled brush and by hosing occasionally with clear, cold water.
2. Do not apply soaps, detergents, cleaning fluids or insecticides.
3. Keep petrol, oil, solvents, kerosene and other similar fluids away from the fabric.
4. Do not allow bird droppings, earth, sand, or vegetable matter to remain in contact with the fabric.
5. It is important that an Outlook awning or blind is let down to dry after wet weather and should not be rolled up or stowed away when wet. Outdoor furniture and cushions should also be dried before storing away.

STUBBORN STAINS: CLEAN THOROUGHLY WITH NON-ABRASIVE HOUSEHOLD CLEANERS, DILUTED RUBBING ALCOHOL OR DILUTED BLEACH - 1:20 CONCENTRATION. RINSE IMMEDIATELY WITH CLEAN WATER AND DRY THOROUGHLY.

Extended Limited Warranty

WHAT IS COVERED?

This warranty covers Outlook mesh becoming non-functional due to loss of dimensional stability from exposure to conditions including sunlight and other normal atmospheric conditions. This warranty does not cover gradual fading, discolouration from atmospheric pollution or other debris. Abnormal or excessive fading is covered.

Any defects found with regard to mesh configuration, dimension, strength or colour that exist at the time of initial delivery, must be reported to Ricky Richards within a reasonable period of time before fabrication or installation of the material.

HOW LONG IS THE COVERAGE PERIOD?

The warranty coverage runs for 5 years from the date of installation.



WHAT WILL PHIFER, THE MANUFACTURER OF OUTLOOK MESH DO?

Phifer Wire Products, Inc. will provide new fabric, at no cost, to replace the non-functioning fabric. This warranty does not cover the cost of labour or other consequential or incidental expenses.

This warranty can only be enforced against presentation of the original installers invoice showing fabric reference and colour as well as date of assembly. The correct care procedures (as outlined above) must be followed to ensure that every step has been taken to maintain the Outlook mesh.



letting the outside in...

